


Handling a flooded VR2W receiver

If a VR2W has flooded, then the possibility exists that the case has become pressurized, making the case a potential hazard. Flooding may also cause the internal battery to rupture and become a chemical hazard. The questions below will help you determine if a VR2W case has flooded.



Does your VR2W...

- ... have a puncture or crack in the case?
- ... weigh more than 1.5 kg (3.3 lbs) in air?
- ... make sloshing sounds when it's moved?
- ... have water in it when you opened the case?
(don't open it to check)

Cracked?

Heavy?

Sloshing?

If you answered “yes” to any questions above then:

1. Do not open the VR2W case. ***If you already opened it, then close it immediately.***
2. Dispose of the VR2W in accordance with local environmental laws.
3. If you come in contact with the chemicals expelled from a ruptured battery, or if clean-up is required, read the [Lithium Batteries MSDS](#) for proper First Aid and handling instructions.

**DO NOT
open, clean,
or ship
a flooded
VR2W.**

Flooded VR2 receiver? If it's in a black case, then use the VR2W instructions above. If it's in a grey case, then go to http://www.vemco.com/pdf/vr2_flooded.pdf.

VEMCO Division, AMIRIX Systems Inc.

221 Horseshoe Lake Drive, Halifax, Nova Scotia, Canada B3S 0B9 Tel: (902) 450-1700 Fax: (902) 450-1704

www.vemco.com